


where tested and
intendent.

The safety valve chest & main & donkey feed chests
& other mountings as per list W75-0136

Response.

Amend Boiler particulars as
follows:- G.S. 38 A.S. 1125. 2 P.F.

B.R.



7/8/29. © 2020

Lloyd's Register
Foundation

A. Daintith
Engineer Surveyor to Lloyd's

travelling expenses (if chargeable)..... £

Received by me,

30.7.29

Committee's Minute TUE. 13 AUG 1929