

Received by Chief Ship Surveyor 9/1/10 Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME St. S. Watermouth Rpt. M. A. B. No. 6609

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 78.83 Depth "d" 25.62

Framing: Table No. As approved Description Channel

Longitudinal No. 29935 Proportions  $\frac{\text{Length}}{\text{Depth}} = \frac{10.36}{}$

Bridge Deck Sheerstrake as approved.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\pm$  100A.1 (Steel) as recommended.


$\pm$  100A.1 (Steel)

1st (Steel)

1132 Hull 2 Ba 114 u 827 f 167 1136t F.P.T. 126 APT 127t

FK. 68H. Gen. Lloyd at 60 p06 B 120 F 38

B



© 2001

Lloyd's Register Foundation

W752-0199