

Sent to Chief Ship Surveyor 26. 3. 16Received from Chief Ship Surveyor 26 MAR 1916VESSEL'S NAME Spuss SmeatonRpt. SkulNo. 29196

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

DAMAGE.

This vessel is reported by the Skul Surveyor to have sustained damage to forecastle side plating through Collision. Temporary repairs have been effected to her his satisfaction to enable her to proceed on her voyage to

The ~~Surveyor recommends~~ vessel has been examined in dry dock & the bottom cleaned & coated, as the Surveyor recommends permanent repairs be effected at the first convenient opportunity.

It is submitted the vessel appears worthy to remain as classed with view of Survey 3.16 subject to above as recommended.

100A-1.

3.16 Skul

} subject to



© 2021

 Lloyd's Register
 Foundation

W753-0152