

Stl. Sc.Sr. "SPIRAL" (Contd).

53 frames removed, faired and refitted, and 2 part removed, faired and refitted, and 182 faired in place. 69 reverse frames renewed; 154 removed, faired and refitted, and 3 faired in place. 40 floors renewed and 160 part renewed; 155 removed, faired and refitted. 165 faired in place. 3 beams removed, faired and refitted, and 18 faired in place. 4 Stringer plates removed, faired and refitted; 1 faired in place. 1 deck plate renewed and 2 faired in place. Centre Girder, intercostals, tank margin plates, tank top plating, etc, repaired and renewed as necessary. A bower anchor, a stream anchor, and a kedge anchor of proper weight and test placed on board.

It is submitted for the favourable consideration of the Committee that the vessel appears worthy to be classed 100.AL., with record of Survey 10,15, and notation of S.S. Hpl. No.3- 10,15.

100 A.1

10.15 Hpl.

SS Hpl. No 3-10-15,

1 St. (Stt.)

37. 10. 15.

WB- Cell DBa 54' 4" E 26' f94 305t A.P.T 17t.
FK, 4 BH, "C'm" 4000 A 16 P' P9, B102, F28,



© 2020

Lloyd's Register
Foundation

W755-0149