

Engine Room ... }
Gross Tonnage 274.08
Less Crew Space 73.25
Engine Room ... }
2669.83

Depth "d," at middle of length (See Secs. 2 & 13) ...
Proportions—Depths to Length—Upper Deck Beam at side to top of keel } 12.04

Manager (Where necessary to be entered in Reg. Book)
Residence Paris

LOYDS REGISTER
LONDON
REC 18 JAN 1913
ANS

COPY.

Time of Receipt

2 53

Lloyd's Register of British & Foreign Shipping,
71, Fenchurch Street, E.C.

16th January, 1913.

ENCLOSURES

Gentlemen,

I am in receipt of your letter of the 15th instant relative to the new French Steamer "SOCOA", and have to confirm my telegram in reply as follows:-

"SOCOA certificates on forms B and B1 may be issued to Builders on payment of all fees please wire when paid certificates following tonight".

I have since received your telegram "fees all paid", and I enclose herewith the first entry certificates for hull and machinery of the vessel to be handed over to the Builders in due course.

I am, Gentlemen,

Your obedient servant,

Secretary

The Surveyors,

SUNDERLAND.



© 2020

Lloyd's Register
Foundation

W-55-0221-22

BEAMS, Second Deck, Single Angle, Bulb Angle, Plate, Tee Bulb, or Channel

Deck. Material & thickness
Poop Deck Stringer Plate, breadth & thickness