

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 15th Dec 1908 When handed in at Local Office 15th Dec 1908 Port of Hull

No. in Reg. Book Survey held at Hull Date, First Survey 22 Dec Last Survey 5th Dec 1905 (No. of Visits 3)

on the Wood, Iron or Steel S.S. Dummergill Master ✓

TONNAGE:-

GROSS 256

UNDER DECK 148

NET 97

Built at Dundee By whom Dundee S.B.C. Ltd. When 1908

Owners Hamilton Shipping Co. Ltd. (Q. Snoddy, Mgr.) Port belonging to Liverpool.

Owners' Address

(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Name of Dock Earls Shipway Destined Voyage ✓

WB=Cell DBorDBa feet; uE&amp;B feet; f feet;

total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
100 A 1 (Contemplated)		

Society's Freeboard (if assigned) as painted on Ship and now verified } ✓ ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? also whether any damage report was made, and, if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of Survey of Classification, See Secretary's letter dated 24th Nov 1908.

The top of the engine and boiler casing has been riveted, and the necessary pillaring fitted in the machinery space

## SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

## PRESENT CONDITION OF THE

	Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt.) When put on, Month Year
Decks	Inner Bottom Plating	Engine Room Skylights	Boats
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Waterways	State if Tanks now tested	Scuppers	Condition now ascertained (State if wedges removed)
Coamings	Bulkheads	Cargo Hatchways	Sails
Beams & Fastenings	Ceiling	Hatches	Equipment Litter
Outside Plating	Cement or Asphalt (State which.)	Planking	Anchors, No. of
Caulking of ditto	Rudder	Caulking	Cables (State if now ranged)
Rivets	Steering gear and its connections	Treenails	" length (on board) size
Breasthooks & Crutches	Windlass	Breasthooks & Stemson	" Rule length (per Table 22) size
Transoms	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Hawser & Warps
Frames	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	Standing & Running Rigging
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	
Floors		Stringers, Clamps & Shelves ditto	
Keelsons		Salting (State if examined.) ditto	

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,07," or "to remain as classed and to have record of survey, 1,07, and the notations of ss No. 1-07 and ptND07, &c."

This vessel appears to be in a good and efficient condition, eligible in my opinion for the class contemplated, and to have record of survey 12.08 in the Register Book.

Survey Fee (per Section 25) £

Special Damage or Repair Fee (if any) (per Sec. 25) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

19

Received by me,

19

Allison B. Wilson

Surveyor to Lloyd's Register of British &amp; Foreign Shipping.

Committee's Minute

FRI. 18 DEC 1908

TUES. 22 DEC 1908

Character Assigned

100 A 1

W758-0028

© 2020

Lloyd's Register  
Foundation