

Committee's Minute
Character Assigned

FRI APR 27 1922
FRI APR 27 1922
FRI APR 27 1922

Deferred for
completion no. 2

1700

LR

Lloyd's
Found

7700-9975

No Complete SS No 2. —

Also ^{Size} bunkers to examine, (ceiling flip)

Tanks under engine and boiler spaces and Cross Hunter to be examined
Shelter deck at fore end of Saloon on port side and plating on port and
starboard side forward to be dealt with and the steam anchors to be made
workable

The owners representative states that arrangements will be made to complete the 55 No 2 on the vessels return from her present voyage.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT, EX. STOCK.			WEIGHT OF STOCK.			TEST, PER CERTIFICATE.				WEIGHT REQUIRED by TABLE 30 or 31.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons.	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower ...																
	2nd ..																
	3rd ..																
	Collective Weight.																
	Stream																
	Kedge.....																

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]