

3m,12,16.

Received by Chief Ship Surveyor 22.2.17

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME

Shewess Stock Iron

Rpt.

San

No. 7982

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey \_\_\_\_\_

The Dundee Surveyor should be requested  
by wire to state whether the stroke of plating  
below sheestake has been increased or as required  
for the omission of side stringers.

Lr 22.2.17.

M  
22.2.17



© 2020

Lloyd's Register  
WATD - 0001  
Foundation