

WOOD 5 MST. SCHOONER "SANTINO".

It is submitted that as the propeller shafts have been removed and the stern tubes permanently blanked off, this vessel should be recorded as a sailing vessel only.

A. R. J.

29.4.20.



© 2021

Lloyd's Register
Foundation

W775-0058