

11783-0044 C1/2

Rotterdamsche Droogdok Maatschappij.

SHIPBUILDERS - ENGINEERS - REPAIRERS.

PRIVATE FLOATING DOCK.

DOCKYARD

Rotterdam.

August 19th 1919

Messrs Lloyds Register,
71 Fenchurch Street

London.

Sirs,

S.S. "VICTORIEUX"

We enclose herewith Profile, Section and Deckplans for vessel, shewing the scantlings in way of damage.-


This vessel was the "Uckermark", two steel decks, Longitudinal Framing, port of Registry Hamburg. She was built by Bremer Vulkan Vegesack to Germanischer Lloyd's requirements in 1911.- After she was running under the Allied Flag as the "Alentejo", under that name she received very heavy fire damage, as indicated on the drawings.- The ship is practically to reconstruct from the bilge upwards.- The new Owner desires this vessel to be classed 100 A1 at the completion of the repairs.-

We should like to know as early as possible, if, the scantlings on the drawings being maintained, the repairs executed to the satisfaction of your surveyor here, you are prepared to class the vessel, and if not, what recommendations you think necessary.-

The double bottom is intact, and will of course be open to examination here.-

Should you desire further information as to scantlings,

As specified differently in writing, our offer is always based upon, and the order is only accepted by us on the following general conditions of Shipbuilders and Engineers of Rotterdam and Neighbourhood, on which conditions the order is understood to be given. (See enclosure).



© 2020

Lloyd's Register
Foundation

Amsterdamsche Droogdok Maatschappij, aan Lloyds Register

... please let us know and we will let you have the parti-
the greatest possible despatch. For your further in-
will send on a shell expansion plan in the course

you in anticipation, we remain, dear Sirs

Yours faithfully,

AMSTERDAMSCHER DROOGDOEK MAATSCHAPPIJ

DIRECTEUR

[Handwritten signature]



© 2020

Lloyd's Register
Foundation

W483-8044 (2/2)

Referred to the Chief Ship Surveyor.

C.S.S.

23/8/19

Reg. rank repy

Received by the

Yachtmaster

on the 23rd inst. in the course of the survey of the coast of the United Kingdom.

© 2020 Lloyd's Register Foundation