

Chief Ship Surveyor 4.12.16

Received from Chief Ship Surveyor _____

L'S NAME Steel s.s. Rinaldo Rpt. Port Said No. 1191

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey DAMAGE. 1st s.s. No 2 due 9.16

This vessel is reported by the Port Said Surveyor
to have sustained ^{slight} damage to poop deck plating through fire
~~Temporary repairs have been effected to his satisfaction to enable her to proceed on her voyage to~~

~~The Surveyor recommends~~

Roeking has been done at this time towards the 1st s.s. No 2 due 9.16

It is submitted ~~action~~ be deferred & the Owners asked to state what arrangements they propose to make for the 1st s.s. No 2 to be held & for the poop deck plating to be examined & dealt with as required.



A.P.
6.12.16
19

Lloyd's Register
Foundation
W789-1004