

# Particulars of Examination and Repairs (if any)

S.S. No. 1.

10001.

Stm. Trawler.

Medical Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on amount of Damage (the cause of which must be stated) should be reported.

30 JUN 1939

2 E

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SEL'S NAME

"ST. ACHILLEUS".

Rpt.

Hul.

No. 50034.

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

ure of Survey ~~COMPLETION OF~~ SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. 1

This Survey, due 12, 38

now held  
partly

now

~~completed~~, and the following repairs carried out (due to wear and tear):-

Some boiler tubes, stays and rivets renewed and minor repairs.

It is submitted the vessel is eligible to remain as classed, with notation of ~~LMC~~ 6, 39 as recommended.



© 2020  
29.6.39

Lloyd's Register  
Foundation

179-0135

examined together with outside fastenings, prop  
sternbush, all found or placed in good order.  
... ..