

Sent to Chief Ship Surveyor 11.1.18

Received from Chief Ship Surveyor 12 JAN 1918

VESSEL'S NAME

M. J. S/S "Roscommon"

Rpt. Wln

No. 301

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey


DAMAGE.

This vessel is reported by the Wellington Surveyor to have sustained damage to No. 1 hatchway &c. through heavy weather Partial Temporary repairs have been effected to his satisfaction to enable her to proceed on her voyage to Australia.

The Surveyor recommends that the repairs be completed at the final port of discharge.  
(The vessel is stated to have since sunk.)

It is submitted the vessel appears worthy to remain as classed without record of survey subject to permanent repairs as recommended.

As now Subject &c.



W790-0083

© 2020

11-1-18

Lloyd's Register  
Foundation