

Am. S. 12

Since foundered

Received by Chief Ship Surveyor 14. 12. 13.

Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel S.S. "RIVER MEANDER" Rpt. N.Yk. No. 9797

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Disclassified Vessel

W. 45 (Bottom)

The New York Surveyors report that they have examined this vessel afloat owing to damage to cargo in No. 3 tween decks, and some minor repairs have been effected.

The vessel is since reported to have foundered, and her class was expunged from the Register Book on the 13th instant.

It is submitted that no action is necessary.



© 2021

Lloyd's Register Foundation

14. 12. 13.

W795-0032

Surveyor to Lloyd's Register.

to remain as classed