

Received by Chief Ship Surveyor 30/10/09. Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME 5th S.S. "Queen" Rpt. Bry No. 10895.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey DAMAGE.

Damage through grounding

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....	1						
Removed and faired or repaired.....	1						
Faired or repaired in place.....		5					

Other items:- Bottom cleaned & coated.

M/M Box 798

It is submitted the vessel is worthy to remain as classed with record of Survey 10-09 Bry as recommended

100 A1  
Spar deck  
10-09 Bry

Mr. R.H.  
30/10/09



© 2019

Lloyd's Register  
Foundation

FRI. 12 AUG 1910

Spar deck

note