

This vessel was built in 1918 and classed 100A1.
The class was withdrawn at the Owners' request
in 1921.

The greater part of a Reclassification Survey
S.S. No. 3 was held at Baltimore in January last, and notations
of 100A1 (Reclassification contemplated) and 'Examined 1.41'
have been assigned by the American Committee.

It is understood the vessel has since been sunk.

The fee for the Reclassification Survey
on the hull, in accordance with the revised practice as approved
for these Ministry of Shipping cases, is £110. A proportionate
fee for the work done at Baltimore, on the Surveyors' estimate
as per Report, is \$300 or £75, and it is submitted this amount
be now charged.

[Signature]
20.4.41

*The Electrical installation, B. shaft and about
2/3 of the engines were surveyed at Baltimore.
Submitted £37 be charged for these services.*

[Signature] 20/4/41



© 2020

Lloyd's Register
Foundation

WP-0204