

Port of Baltimore

December 18th 1940

REPORT ON MASTS, SPARS, AND RIGGING.

Dear Sirs

Having, in accordance with your instructions, examined
Masts, Spars, and Rigging, and Iron Work of same, of the
Ss Black Osprey.

I have the honor to report that I found All Rigging in good
condition with the exceptions as under noted.

1) Two forward & (2) After Midships stays
on Foremast in bad condition corroded

2) Two forward & (2) Two After stay Midships
on Main Mast in bad condition Corroded

3) Sixteen Turnbuckles of various sizes
to be overhauled.

David D. Campbell

Surveyors,
Lloyd's Register of Shipping,



© 2020

Lloyd's Register
Foundation

WS-0206