

PORT 5

1m.4.34.

UKSO-0014

4 E

Received by Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

VESSEL'S NAME "SARANAC".

Rpt. Bel.

No. 12584.


The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

S.S.No.2, due 3,39, partly held 11,38)
Boiler Survey, due 11,39, partly held 9,39 } -completed.

It is submitted the vessel is eligible to remain as eligible for the record classed with records ~~LMC~~LMC11,38, BS9,39 and WILL BE BS3,40 when ~~the~~ both forward boilers have been surveyed.



Lloyd's Register Foundation

[Signature]
28.3.40.