

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

4 E

VESSEL'S NAME

"SARITA"

Rpt. Rot.

No. 28836

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 2415(92).)

Nature of Survey

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH HEAVY WEATHER.

Some crank shaft coupling bolts renewed.

Main engine pump lever gear refitted.

It is submitted the vessel is eligible to remain as classed.

SS No 3 due 7.39.
Year of frace approved.



© 2020

Lloyd's Register
Foundation

13.3.40

13 MAR 1940

VPO-0098