

declined?

Was a damage report made by anyone else? If so, by whom?

13,000,491

W/ 801

W B 32 Top

Received by Chief Ship Surveyor

21/1/10

Received from Chief Ship Surveyor

VESSEL'S NAME

St. C. S. Pericles

Rpt.

Low

No.

72304

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Condition

This vessel has been examined in dry dock the bottom cleaned & repairs & minor repairs done.

It is submitted the vessel appears worthy to remain classed with record of survey as recommended.

The double bottom requires to be examined by the Society's Surveyors periodically.

100 A1 Lion as with 7th
1-10 Low



© 2001

Lloyd's Register
Foundation

W801-0044