

Report *Nov 24 1904* When handed in at Local Office *1904* Port of *London*
Survey held at *London* Date, First Survey *Nov 10* Last Survey *Nov 17 1904*
on the Wood, Iron or Steel *S.S. "STAR OF SCOTLAND"* (No. of Visits *2*) Master

Owners Address
(If not already recorded in Appendix to Register Book.)

Afloat or in Dry Dock? *Afloat* Name of Dock *Royal Albert* Destined Voyage *Australia*

(D Box D Ba feet: 4 E & B feet: 1 feet: 1)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Year Assigned	Year expired.	Machinery and Boiler Surveys (including date of N.B., if any).
* For Special Survey. Date of last Survey and of Periodical Surveys.			

Report, No. _____	Port _____	<div style="text-align: right;"> <i>Hood-1.</i> <i>Class</i> <i>6 Contemplated</i> </div>
<p>surveys, when held, must be reported <u>in detail</u> and <u>seriatim</u> in the terms of the Rules. State clearly the nature, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs of Damage (the cause of which must be stated) should be separated from Repairs due to other causes:</p>		

being detailed in the body of the report, should be summarised in the form shown below. Whenever the use of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified } 6 ft. 6 in.

uses where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were not accepted. Also whether any damage report was made, and, if so, by whom?

OR EXAMINATION AS PER RULE, FOR Steering Gear. See letter Belfast
eyes of Oct 31st 1904.
done:- Steering gear chain drums of increased size
id to the steering gear. and the chains lengthened
int larger diameter

DAMAGE REPAIRS :—		Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
... ..									
nd Fair'd or Repaired									
epaired in place									
TION OF THE		Stringers				Db'ing. Plates under Sounding Pipes.			Copper, or Y.M. of Wood Vessels.
		Inner Bottom Plating				Engine Room Skylights.			(State if on self.)
		State if Tanks have been examined inside				Coal Bunkers, Open'gs, Lids, &c.			When put on, Month Year.
		State if Tanks now tested.				Scuppers.			Boats.
		Bulkheads				Cargo Hatchways			Masts, Yards, &c.
		Ceiling				Hatches			Condition, how ascertained
		Cement or Asphalt				Planking of Wood Vessels.			(State if wedges removed)
		(State which.)				Caulking ditto.			Sails.
		Rudder				Treenails ditto.			Equipment letter
		Windlass				Breasthooks & Stemson ditto.			Anchors, No. of
ches		Have Pumps now been examined and found efficient?				Transoms, Pointers, & Crutches ditto.			Cables (State if now ranged)
		Have Sluice Valves now been examined and found efficient?				Timbers of Frame at openings ditto.			" length size
						Ditto ditto at other places ditto.			(on board)
						Stringers, Clamps & Shelves ditto.			" Rule length size
						Salting ditto.			(per Table 22)
						(State if examined.)			Hawsers & Warps.
									Standing & Running Rigging

Observations, Opinion as to Class, Recommendation, &c.:—

clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon thus, for example:—".....to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptd98, &c.."

alone is for the information of the
committee

able) per Scale II, Sec. 27£	:	:	Fees applied for,
ation 28)£	:	:19.....
Repair Fee (if any)£	:	:	Received by me,
(if chargeable)£	:	:19.....
re (if any)£	:	:

George. J. Robson
Surveyor to Lloyd's Register of British & Foreign Shipping.

3 Minute
Assigned

TUES. 6 DEC 1904
FRI. 9 DEC 1904

Lloyd's Register
W803-0063