

fitted at the first opportunity.

In adjusting the safety valves it was noticed that those of the Starboard boiler lifted at 185 lb, the working pressure per Register Book being 192 lb. as the washers are solid rings no alteration could be made at the time.

P. F.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

P.F.
18.4.18



© 2021

Lloyd's Register
Foundation