

Cochrane's 'Is No. 590.

Submitted Messrs. Fellows be informed that the head of each stockless anchor is required to be three-fifths of the total weight of the anchor, and as the head of the 2nd bow is practically 5% below the required weight it cannot be accepted ~~for~~ for the figure 1 for equipment.

If the total weight of an anchor is in accordance with the Society's requirements, and the weight of the head not less than $\frac{3}{5}$ $\frac{1}{2}$ of the total weight, ~~the anchor would~~ and the anchor satisfactory withstood the tests in accordance with Table 38 it would be approved for the figure 1 for equipment.

24/1/14

Ans 26/1

H. Hull.



© 2021

Lloyd's Register
Foundation

W807-0098