

La Constructora Naval Espanola nos

23 & 24

Apr 11908.

Submitted that copies of these
reports be forwarded to the
Cadiz Surveyor for completion.

Mr. Copies of Sur-
reports to Mr. S.
13/10/08
50



© 2021

8.8.02

Lloyd's Register
Foundation

W812-0047

diameter of rivet holes in long. seams 1 7/16 Pitch of rivets

4 7/16

Lap of plates or width