

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report *April 3<sup>rd</sup>* 1917 When handed in at Local Office *April 3<sup>rd</sup>* 1917 Port of *New York*

No. in Reg. Book. *65* Survey held at *Off Red Hook* Date, First Survey *Apr* Last Survey *April 3<sup>rd</sup>* 1917  
*Supp* on the *Wood, Iron or Steel* *Sp L. L. L.* Master *D. Maggi*

TONNAGE:— Built at *Napoli* By whom *Milieu Bishi Dlya & Co* When *1916* MONTH *11*  
GROSS *7212* Owners *Stella Nazionale di Navigazione* Port belonging to *Genoa*  
UNDER DK. *6517* Owners' Address *(if not already recorded in Appendix to Register Book)*  
NET *5348*

Surveyed Afloat or in Dry Dock? *Yes* Name of Dock *New York Harbour* Destined Voyage *Genoa via Philadelphia*  
WB=Cell DBor DBa feet; uE&B feet; f feet; } Particulars of Classification (which must be inserted  
total capacity (tons. FPT tons. APT tons; MT feet tons.) precisely as in Register Book & Supplements).

N.B.—All alterations to the existing records should be underlined.  
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.  
Last Report, No. *3643* Port *Genoa* *100.A.1. 11-16* *L.M.C. 11-16*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)  
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Condition*

*Vessel examined afloat as far as practicable. Decks, hatchways, hatches, holds, masts, spars & rigging & equipment examined and all found in good order.*

*WB25 TOP*

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fairied or Repaired								
Fairied or Repaired in place								
PRESENT CONDITION OF THE								
Decks	<i>Good</i>	Stringers	<i>Good</i>	Dblg. Plates under Sounding Pipes	<i>Good</i>	Copper, or Y.M. of Wood Vessels		
Caulking of Decks		Inner Bottom Plating		Engine Room Skylights		(State if on Felt.)		
Waterways		State if Tanks have been examined inside	<i>No</i>	Coal Bunkers, Open'gs, Lids, &c.		When put on, Month	<i>Good</i>	
Coamings		State if Tanks now tested	<i>No</i>	Scuppers		Boats		
Beams & Fastenings		Bulkheads	<i>Good</i>	Cargo Hatchways		Masts, Yards, &c.	<i>From deck</i>	
Outside Plating	<i>As per rule</i>	Ceiling		Hatches		Condition, how ascertained	<i>From deck</i>	
Caulking of ditto		Cement (State which.)		Planking of Wood Vessels		(State if wedges removed)	<i>No</i>	
Rivets		Rudder	<i>Good</i>	Caulking	ditto	Sails	<i>Good</i>	
Breasthooks & Crutches		Steering gear and its connections	<i>Good</i>	Treenails	ditto	Equipment letter	<i>34</i>	
Transoms	<i>Good</i>	Windlass		Breasthooks & Stemson	ditto	Anchors, No. of	<i>33 1/2</i>	
Reverse Frames		Have Pumps now been examined and found efficient?	<i>Yes</i>	Transoms, Pointers, & Crutches ditto		Cables (State if now ranged)	<i>No</i>	
Floors		Have Sluice Valves now been examined and found efficient?	<i>Yes</i>	Timbers of Frame at openings ditto		length (on board)	<i>34</i>	
Keelsons		Have Watertight Doors now been examined and found efficient?	<i>Yes</i>	Ditto ditto at other places ditto		Rule length	<i>Complete</i>	
				Stringers, Clamps & Shells	ditto	Hawser & Warps	<i>Good</i>	
				Setting (State if examined.)	ditto	Standing & Running Rigging		

General Observations, Opinion as to Class, Recommendation, &c.:—  
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1, 15, and the notations of ss No. 1-15 and ptnp15, &c."  
*This vessel is now in a good & efficient condition. Eligible in my opinion to remain as classed without fresh record of survey.*

Survey Fee (per Section 28) *Certificate \$25.00*  
Special Damage or Repair Fee (if any) (per Sec. 29)  
Travelling Expenses (if chargeable)  
Second Surveyor's Fee (if any)  
Fees applied for, *5.4 1917*  
Received by me, *A. Hudson*  
Surveyor to Lloyd's Register of Shipping.

Committee's Minute  
Character Assigned *As now*  
New York APR 12 1917

