

Office : 71, Fenchurch Street, London, E.C.

Port of Fiume.

March 17th. 1919.

for examination of repairs

mended that the record of +L.M.C. 3.19 and tail-

Register Book in the case of this vessel.

M. Bannister

Engineer Surveyor to Lloyd's Register.

terms of the Rules and Regulations of the Society, which provide that :—
 "The Society shall endeavour to ensure that the functions of the Society are properly executed, it is to be understood
 that the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or
 Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of
 Surveyors, or other Officers or Agents of the Society."

W831-0053