

11 OCT 1917 ¹

Ship Surveyor 9.10.17

Received from Chief Ship Surveyor

1E Shells Lodanor

Rpt. live

No. 70326

of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also pointing out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points noted in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.

DAMAGE.

through Collision & grounding

desired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
.....							
and faired							
paired.....							
or repaired	4						
ace.....							

Items:- Vessel examined in dry dock. Large keels repaired & minor repairs carried out. A bronze anchor & 15 fathoms of chain supplied.

Condition. Bottom cleaned & coated & vessel generally examined.

Some indentations plating require to be dealt with at a favourable opportunity.

On 3 Dec 5.17, no part of survey held

submitted the vessel is worthy to remain as classed with

Board of Survey

as recommended

action be deferred



© 2020

Lloyd's Register Foundation

W832 - 0079