

COPY.

Received 12th January, 1914.

Answered

LETTER received from the Society's Surveyor, GIBRALTAR.

dated 7th January, 1914.

Sir,

With reference to the inquiries contained in your letter S. dated 2nd instant respecting "FACI" and "MARAKCHI", "FACI", All thrust shoes remetalled and thrust collars turned up in lathe.

All pumps examined and in good condition in both ships and notation to this effect in Reports was omitted due to a clerical error.

"MARAKCHI". Rhrust collars and haft were examined and thrust adjusted, but as it was not necessary as in the case of "FACI", to remetal or true up shaft this was not specifically mentioned.

I am, etc.

(Signed) W.H.Beckett.



© 2020

Lloyd's Register  
Foundation

W835-0065