

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 20 Dec. 1913 When handed in at Local Office 10 Port of Gibraltar

No. in Reg. Book 382 Survey held at on the Wood, Iron or Steel S.S. "Marachi" Date, First Survey 9. 12. 13 Last Survey 10. 13

TONNAGE:—  
GROSS 53  
UNDER DK. 150  
NET 68

Build at Selby By whom Bochrane & Sons When 1911

Owners G. G. G. G. Port belonging to Tangier

Owners' Address Admiralty Destined Voyage Morocco ports

Surveyed Afloat or in Dry Dock? dry dock Name of Dock Admiralty

WB=Cell D Bor DBa — feet; uE&B — feet; f — feet;  
total capacity tons. FPT — tons; APT — tons; MT — feet — tons.

Last Report, No. 24, 287 Port Senegal

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER	Assigned	Machinery and Boiler Surveys
* for Special Survey, Date of last Survey and of Periodical Surveys		(including date of N.B., if any)
<u>+100 A1</u>	<u>9. 11</u>	<u>+L. inc</u>
		<u>10. 11</u>

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the inside of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Society's Freeboard (if assigned) as painted on Ship and now verified — ft. — ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? — Was a damage report made by anyone else? If so, by whom? —

REPAIRS OR EXAMINATION AS PER RULE, FOR Annual Survey in dry dock  
Hull externally in good condition generally - Bottom & rudder cleaned & afterworks recast with composition. Rudder pintles renewed.

Internal surfaces of bulk plates & frames are in good condition as far as could be seen without removal of linings or cement.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	E. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or I.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on felt.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Scuppers	Boats
Coamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained
Outside Plating	Cement or Asphalt (State which.)	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	Rudder	Caulking ditto	Sails
Rivets	Steering gear and its connections	Treenails ditto	Equipment letter
Breasthooks & Crutches	Windlass	Breasthoeks & Stenson ditto	Anchor, No. of
Transoms	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	" length size
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	" Rule length size
Floors		Stringers, Clamps & Shelves ditto	Hawser & Warps
Keelsons		Salting ditto (State if examined.)	Standing & Running Rigging

### General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,11," or "to remain as classed and to have record of survey, 1,11, and the notations of ss No. 1-11 and pnd11, &c."

To continue as now classed with fresh date +100 A 1 12/13

Survey Fee (per Section 28)	£	
Special Damage or Repair Fee (if any)	£	1 0 0
Travelling Expenses (if chargeable)	£	
Second Surveyor's Fee (if any)	£	

Fees applied for, 30/12/13  
Received by me, W.H. Bockett

Surveyor to Lloyd's Register of British & Foreign Shipping

Committee's Minute

FRI. JAN. 2 - 1914

FRI. JAN. 16. 1914

Character Assigned as per

WELL CERTIFICATED WRITTEN



Yes to Surveyors please

W835-0066