

Received by Chief Ship Surveyor 12.7.15

Received from Chief Ship Surveyor _____

VESSEL'S NAME Shells "Marowijne" Rpt. L. S. No. 1165

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

Nature of Survey _____

Damage through propeller striking some submerged object

now repaired as follows:-

| | Plates | Frames | R. Frames | Floors | Beams | Str. Plates | Dk. Plates |
|--|--------|--------|-----------|--------|-------|-------------|------------|
| Renewed | | | | | | | |
| Removed and faired or repaired..... | | | | | | | |
| Faired or repaired in place..... | | | | | | | |

Other items:-

Vessel examined in dry dock, bottom
hull cleaned & repainted

It is submitted the vessel is worthy to remain as classed with
record of Survey 6.15 as recommended

100A.1. Sp. Dr.

6.15 L. S.



© 2021

Lloyd's Register
Foundation

W838-0016