



*Wreck Co*  
PHONE LOMBARD 3543  
267  
26  
91.

LLOYD'S REGISTER OF SHIPPING,

449-450, BOURSE

PHILADELPHIA, April 28th, 1917.

Secretary,

New York.

Dear Sir:

In reply to your letter of the 25th inst., regarding report No. 2523, on the Steamer "MALMANGER", I beg to state that as the cellular double bottom was arranged for carrying oil, the inner surface of the shell plating in way of same was not coated.

Yours very truly,

*James B. Butler*

LLOYD'S REGISTER  
NEW YORK

REC'D APR 30 1917

ANS'D \_\_\_\_\_



© 2020

Lloyd's Register  
Foundation

W839-0015