

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

8th October, 1918.

Dear Sir,

With reference to Liverpool Reports Nos. 78197 and 78198 on the trawlers "NJORDUR" and "SNORRI STURLUSON", I shall be glad to learn whether the Surveyor is correct in reporting that these vessels have only 75 fathoms of $1\frac{5}{16}$ chain cable on board, in view of the fact that the "NJORDUR" was originally supplied with and still requires 105 fathoms of $1\frac{1}{16}$ and the "SNORRI STURLUSON" 90 fathoms of 1 inch chain cable.

I am, Dear Sir,

Yours faithfully,

Secretary.

The Secretary.

LIVERPOOL.



© 2021

Lloyd's Register
Foundation

W 852-0122