

WB
tota

3m.7.14.

1

Received by Chief Ship Surveyor 19. 2. 15

Received from Chief Ship Surveyor _____

VESSEL'S NAME J.H. & Co. "Neptunian" Rpt. Hul No. 28288

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DAMAGE.

Damage through

Grounding

M. J. B. 855

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....	<u>3</u>						

Other items:-

Vessel Examined on Slipway, bottom
Accrated & minor repairs
Effectid

It is submitted the vessel is worthy to remain as classed with record of Survey 2 15 as recommended

100 A. 1
5th Hawker
2 15 Hul.

M. J. B. 855
19. 2. 15



© 2020

Lloyd's Register
Foundation

W855-0047

10m.114.—77
requested not to work