

1

Wreck 20

WRECK BOX
No. 20 (top).

Sent to Chief Surveyors 3.7.17

Received from Chief Surveyor

VESSEL'S NAME Sheels Hunbridge

Report Lis

No. 76616

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey Damage

When due

Some indentations plating requires to be dealt with.

The ss has become due in July 1916, but nothing has been done in regard to same at this time.

M
4.7.17



© 2020

Lloyd's Register
Foundation

W856-0001