

5 OCT 1917

of Surveyors 4. 10. 17.

Received from Chief Surveyors _____

NAME S.S. "Hungenford" Report C/B No. 39854

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Survey S.S. nos. When due 3. 7. 17. &c

The Special Survey nos. became due in March 1917. The machinery survey has been held. Some damage requires to be permanently repaired.

The Belfast Surveyors now state they are informed the Owners do not expect to have an opportunity of carrying out the Special Survey on the hull until the vessel is released from her present charter after the war.

It is submitted action be deferred for the present



© 2020
4. 10. 17
Lloyd's Register
NW856-0140
Foundation

This Cer
" While if
that neither th
certificate is su