

Received by Chief Ship Surveyor

1. 5. 16
18. 4. 17

Received from Chief Ship Surveyor

VESSEL'S NAME

Steel S. S. House

Rpt.

H

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the

("The endorsement to contain a summary of any repairs that have been required and to show the cause or causes of such repairs, so that the Classing Committee may have all the facts presented in the endorsement."—Extract from Sub-Committee's Report 34/5/92.)

Nature of Survey

DAMAGE.

Damage through heavy weather & carrying an excessive weight in tween decks

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							3
Removed and faired or repaired.....							
Faired or repaired in place.....							3

Other items:-

Vessel examined afloat. Hatchway coamings
in Nos 1 & 3 hold repaired
Minor repairs effected.

It is submitted the vessel is worthy to remain as classed without
record of Survey as recommended



© 2020
Lloyd's Register
Foundation