

WRECK BOX

No. 20,716.

20 (787) wreck 20

Received by Chief Ship Surveyor

5. 12 16

Received from Chief Ship Surveyor

VESSEL'S NAME

St. S. S. "Horn Head"

Rpt.

Sws. No. 14117

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Condition

This vessel has been placed in dry dock the bottom revealed & minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with fresh record of survey as recommended.

100 A. I.  
11. 16. 8 Sws.

5. 12. 16  
Lloyd's Register  
Foundation  
W859-057

to remain as classed with fresh record of survey 11. 16