

total
d by Chief Ship Surveyor 8. 12. 15

Received from Chief Ship Surveyor

9 DEC 1915

EL'S NAME

Steel Fuel Helly

Rpt.

Lon

No. 78405

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Remarks of Survey


The London Surveyor should be requested to state whether the standing rigging has been lifted & the spinnaker & parcelling shipped off the masts, heads, & splices as required by the Rules.

In the London Surveyor.
10.12.15

M
9.12.15

(see note on back of rpt.)

M
13.12.15



© 2020

Lloyd's Register
Foundation

W866-0003