

F.E.

Received by Chief Ship Surveyor 18.3.15

Received from Chief Ship Surveyor

VESSEL'S NAME M.S.S. Millellan

Rpt. Std No. 26378
26391

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 62-5

Depth "d"

Framing: Table No.

Description

Butt angles.

Longitudinal No. 15675

Proportions $\frac{\text{Length}}{\text{Depth}} =$ 12.5

Deck Sheerstrake

And other scantlings as

Approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ± 100 A.1. (Steel) For Coasting Service. British Isles and English Channel as recommended.
± 100 A.1 (Steel) For Coasting Service. British Isles and English Channel.

1 D.K. (M.)

WB. Cell DBH E+B 42' f166' 650t. FPT 365', APT 135'
FK, 5 BH, Cm. Lays a 16 P Q 103' F 39'

Mch 18.15

DATE OF BUILD 1.15

W869-0066



© 2020

MAN. 18.3.15

Lloyd's Register Foundation

1/11