



Lloyd's Register of Shipping,

55, Fawcett Street,

Sunderland, 11th March, 1915.

1 Encls.

The Secretary,

London.

Sir,

I am in receipt of your letter of the 10th instant in reference to the first entry report No. 26378 on the new steamer "KILLELLAN" and beg to state that brackets are fitted at the tank margin in alternate frames in the double bottom tank

The brackets in way of shallow part of double bottom are now shewn on the midship section and the section has now been amended to agree with the report as regards the size of the frames and reverse frames in double bottom at alternate frames.

The Builders state that the vessel is returning direct to Sunderland from Rouen and arrangements are being made to have the additional equipment placed on board on arrival and a report will be forwarded in due course so as to prevent any delay in the classification.

I am, Sir,

Your obedient Servant,

L. S. Atchard

24/7
1 plan
favourable consideration of the Committee for the figure 1.

© 2020

Lloyd's Register

W869-0067

MAR 12 1915

18. 2. 18

127

© 2020

Lloyd's Register
Foundation