

**COPY.**

**Lloyd's Register of Shipping,**

71, Fenchurch Street, E.C.

Enclosure.

10th March 1915.

Dear Sirs,

M With reference to your first entry report No. 26378 on the new steamer "KILLELLAN", I have to inform you it is concluded that brackets are fitted at the tank margin on alternate frames in the double bottom tanks, and I shall be glad if you will indicate on the sketch in way of shallow part of double bottom the size of these brackets. You should also amend the section to agree with the vessel as built and the first entry report, as regards the size of the frames and reversed frames in double bottom at alternate frames.

With reference to the additional equipment required, it is concluded that the vessel is returning direct to Sunderland from Rouen, and that arrangements will be made for this equipment to be examined immediately it is placed on board, and for a report to be forwarded without delay with a view to the classification of the vessel.

The sketch of midship section is returned herewith.

I am, Dear Sirs,  
Yours faithfully,

The Surveyors,  
SUNDERLAND.



© 2020

Secretary.

Lloyd's Register  
Foundation  
W869-0072