

COPY.

H-dept

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.

Enclosure.

2nd July 1915.

Dear Sirs,

M I am in receipt of Mr. Harrison's telegram of this morning, as follows, viz:-


"Steamer IGNIS 33 Supplement in dock after stranding
"off Flambro Bottom badly set up and damaged Salvage
"Association Surveyor alleges part of setting up due
"to previous damage which statement we do not accept
"bottom was dealt with Grimsby April last suggest
"Mr. Martell be instructed meet me at Vessel tomorrow
"morning",

and with regard thereto I have to inform you that in the circumstances Mr. Martell has been instructed by telegram to proceed to your port immediately and join in the survey of this vessel tomorrow morning.

I have therefore wired you as follows, viz:-

"Steamer IGNIS have instructed Mr. Martell proceed
"Newcastle immediately and join in survey tomorrow
"morning".

For your information I send herewith the Grimsby



© 2021

Lloyd's Register
Foundation

W872-0026/2

COPY.

Report No. 9991.

I am, Dear Sirs,

Yours faithfully,

Secretary.

The Surveyors,

NEWCASTLE.



© 2021

Lloyd's Register
Foundation

W872-0026 2/2