

Copy of Dan. rep. S.

S.S. Gerda, Skue rep.  
no. 1621

Stockholm, Surveyor's

Office, 25<sup>th</sup> Oct. 1916

Albert Sakson,

The Owners survey the Danish steel screw steamer Gerda, 775 Gross tons, of Esbjerg, N. Iversen Master, in order to ascertain the nature and extent of the damage, stated to have been sustained through collision with a dock gate at Goole on the 14<sup>th</sup> Sept. 1916, when vessel was entering dock on a voyage from Seville to Goole with a cargo of ore. For further particulars of the casualty see log book.

On the 24<sup>th</sup> October 1916, vessel being taken on the Timbode Pontoon, Stockholm, I examined this damage, found it to be as follows and recommended it to be repaired in the following manner, viz.:

Shell plating on port side

E. stake, plate no. 3 from stem badly indented  
— to be taken out, bent, forced and refitted



© 2020

Lloyd's Register  
Foundation



E. stake, plate no. 4 slightly bent - to be faired  
in place.

3 frames in way of E. 3 plate found very slight-  
ly bent - to be faired in place.

Repaired work to be coated with red lead and  
paint and the ship's side restored in the  
same good and efficient condition as be-  
fore the accident occurred.

Witness my hand

C. L. GATSON

Ship and Engineer Sur.  
U.S. Navy



© 2020

Lloyd's Register  
Foundation

W875-0106-2