

3m.2.11.

Wreck Box 19

WRECK BOX No. 19 TOP

Sunk by collision 7.12

1

Received by Chief Ship Surveyor 20.1.12

Received from Chief Ship Surveyor

VESSEL'S NAME S.S. "Helvetia"

Rpt. Dry

No. 12401

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

Nature of Survey

Damage through grounding & by cargo grabs.

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed.....							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:-

Vessel examined in Dry Dock. Shell caulking overhauled, bottom cleaned & coated. A number of frames (longitudinal) faired in place, & wood casing in way renewed.

It is submitted the vessel is worthy to remain as classed with record of Survey 1.12 Dry as recommended

100 A.1  
1.12 Dry.

Handwritten signatures and date 20.1.12

The Certificate of Classification to have the following words written on it: "This certificate is for the vessel being engaged exclusively in carrying coal, ore, or wood, while without cargo battens"



© 2020

Lloyd's Register Foundation