

Chief Ship Surveyor 24/5/11.

Received from Chief Ship Surveyor

NAME *S.S. "Helvetia"*

Rpt.

Swc.

No. *60354.*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

1st Entry.

It is submitted that, before this case receives the consideration of the Committee, this report should be returned to the Newcastle Surveyors who should be requested to fill in, in the space provided on the report, the scantlings and particulars of riveting of the poop & fore-castle side plating; they should also be requested to state the length of the wing side tanks with a view to its insertion in the Register Book.

Their attention should ^{be drawn} to the size of No. 2 side longitudinal as reported by them & in view of the size approved they should be requested to state if the size reported is correct.

They should also be requested to forward all the plans approved for this vessel.

24.5.11

M

R.A.
24/5/11



© 2020

Lloyd's Register
Foundation

W878-0123