

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Sel Se M/V THORSHOLM* Rpt. *Sld* No. *30472*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

1st Long
Transverse No.

14484

Depth "d"

Framing: Table No.

Description

Longitudinal framing

2nd Longitudinal No.

39222

as approved

Proportions

Length

13

Depth =

Deck Sheerstrake

as approved

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A. I. (Steel). Carrying Petroleum in Bulk
 2 D^{co} (Stl) & Web Frames, Longitudinal framing
 Cell D.B. & E 65' H765, D.T.f 33' H285, F.P.T. 2635, A.P.T. 1035.
 F.K., 16 B.H. (10 B.H. to upper D^{co}, 6 B.H. to 2nd D^{co}), ft cm, Lloyds ACP.
 P 102', B 32', F HH'.
 Machy aft.



© 2021

13.10.30

Lloyd's Register
Foundation

W89-0211