

WB=C
total c
V.E

CABLEGRAMS: NYMDIBLE, NEW YORK.

TELEPHONES { 1363 } RECTOR
 { 1364 }



LLOYD'S REGISTER OF SHIPPING,
17 BATTERY PLACE,

NEW YORK July 31, 1914.

The Secretary,
London.

Sir:-

LLOYD'S REGISTER
LONDON
10 AUG 1914
REC'D 18

In reply to your classing letter of the 24th July, 1914, with reference to the case of the "INDIAN PRINCE", I beg to state that the pump and all sea connections were examined at the time the survey was held, Report No. 10472. Repairs being carried out to several sea cocks and auxiliary pumps as stated on that report, the omission of pumps and sea cocks being examined, being in error.

With reference to examination of tanks, my report No 10856 states in the body of the report that Nos. 1, 3 and 5 tanks were examined. Report No. 10637 states that Nos. 2 and 4 were examined and this completes the whole tank examination.

I am, Sir,

Your obedient Servant,

C. Murray

RECEIVED
JULY 31 1914

PI 21 01-214



© 2020

Lloyd's Register
Foundation

W 890-0055

transfer
Survey

Referred to the Chief Ship Surveyor
and the Chief Engineer Surveyor.

AUG 10 1914

Referred to Mr. S. A. Hill

M
14 p. 14

Handwritten signature

Your obedient servant,

I am, Sir,

examined and did complete the above mentioned examination.
were examined. Report No. 10301. It is stated that the
were in the body of the report that Nos. 1, 2 and 3 tanks

With reference to examination of tanks, my report No. 10301
being examined, being in error.

as stated in my report, the omission of pumps and sea cocks
being carried out to several sea cocks and auxiliary pumps
the time the survey was held, Report No. 10302. Details
state that the pump and its sea connections were examined at
with reference to the case of the "ILLUMINANCE". I refer to

In reply to your circular letter of the 27th July 1914.

Sir:

London.

The Secretary,



© 2020

Lloyd's Register
Foundation

NEW YORK

LOYD'S REGISTER OF SHIPPING
17 BATTERY PLACE

TELEPHONE 1384 1385

REGISTERED MAIL

10/3/10