

Wreck 14.

WRECK BOX

No.

14 Bottom

2

Received by Chief Ship Surveyor

14. 5. 13

Received from Chief Ship Surveyor

VESSEL'S NAME

M.S.S. "Enzie"

Rpt.

Abn

No.

11135

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

S.S. No. 1

The

S.S. No.

has now been held, and the following repairs

done due to wear and tear:-

bottom cracked, stem & stem  
plating joined & minor repairs.

It is submitted the vessel is worthy to remain as classed, with record of Survey 5.13 Abn and notation of S.S. Abn No. 1.13 as recommended.

1000 A.1 "For fishing purposes"


5.13 Abn.

S.S. Abn. No. 1.13

AP

15.5.13

© 2020



Lloyd's Register  
Foundation

W892-D164