



Lloyd's Register of British & Foreign Shipping,

29, Regent Quay,

Aberdeen, 30th June 1908

LLOYDS REGISTER
LONDON.

REC'D 1 JUL 1908

ANSR

The Secretary
London

Sir,

In reply to your letter of the 26th inst. regarding the machinery of the S. O. "Enzie", I beg to inform you that I have made enquiries from Mr. Binet, the manager of the engine shop at Buckie, who was acting for the Owner on the occasion of my visit to this vessel, and he informs me that the new high shaft has fitted and the main shafting coupled up with the new bolts before the vessel sailed for the North fishing last Monday everything at that time being satisfactory.

The Owner of the vessel is also the Master and has sailed with the vessel.

I am, Sir,

Your obedient servant

James C. Chapman

© 2020
Lloyd's Register
Foundation

W842-0179

Referred to the Chief Engineer Surveyor.

CJR

JUL -1 1908

It is submitted That the Aberdeen
Surveyor should be requested
to ascertain on the vessels return
whether the repairs carried
out have proved satisfactory
or if all is ~~and~~ in good
order. In the meantime
action in this case
might be deferred.

A.R.R.

1.7.08



© 2020

Lloyd's Register
Foundation