

Wreck Box 16

28 JAN 1917

1

Received by Chief Ship Surveyor 24.1.17

WRECK BOX 16. Top

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S. S. # Lore Rpt. Cff No. 3934/5

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DAMAGE.

Damage through heavy weather collision

(see above Report 3840)

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	4	3 part				3	
Removed and faired or repaired.....	1				4		4
Faired or repaired in place.....	2	2			3	1	3

Other items:-

Vessel examined in dry dock.

Bottom cleaned and coated.

Rudder rebushed

Steering gear repaired minor repairs effected.

wear & tear:-

Bunkers repaired at necessary

Wardlass renewed

Sounding pipes repaired. minor repairs effected

It is submitted the vessel is worthy to remain as classed with record of Survey 1.17 as recommended

100 A.1.

1.17 Cff



© 2020

Lloyd's Register Foundation

W893-0088